

## Service Bulletin

---

### REVISED

January 18, 2001

Dear Customer:

Service Bulletin No. 68-24 is being issued to correct a duplication error. Please disregard Service Bulletin No. 68-23 entitled **New Service Accelerated Release Filling Piece Gasket**.

Service Bulletin No. 68-24 is being issued to introduce our new Wabtec freight control valve Service Accelerated Release Filling Piece Gasket. This gasket has been redesigned to improve positioning and retention in two key areas. The gasket has been used in all Wabtec facilities since early September 2000.

Please review the attached Service Bulletin. If you have any technical questions or questions about returning old stock please call the Wabtec Customer Service Department at (412) 825-1129.

For future distributions please forward your e-mail address to [ymerdian@wabtec.com](mailto:ymerdian@wabtec.com). Thank you in advance for your cooperation.

Sincerely,

Jeffrey W. Brunson  
Field Engineering Rep.  
(412) 825-1535

Attachment


H:\YMERDIAN\SERVICE BULLETIN\SERVICE BULLETIN 68-24 COVER LETTER REVISED

## AB TYPE SERVICE PORTIONS

### New Service Accelerated Release Filling Piece Gasket

September, 2000

A design upgrade to the Service Accelerated Release Filling Piece Pc. No. 0563997 gasket has been completed. The new configuration consists of a reduced diameter of the center hole to provide improved positioning, and the addition of two brass inserts to improve the retention of the gasket in two areas.



Wabtec recommends that all existing stock of the old configuration gasket be replaced with the new configuration gasket. The new gasket retains the same part number, Pc. No. 0563997. Please contact Diane Kowalski at 412-825-1129 for further information.