

SAC-1™**Spherical Articulated Coupling****Ball Inspection**

JULY, 1998

When the bearing assembly is removed for bearing replacement, inspect the working surface of the ball.

The ball is to be cleaned of dirt and/or old bearing material residue and **reused**. If there is any indication of metal to metal, contact with the race in the work area, the ball must be replaced.

Questions concerning this bulletin should be addressed to Cardwell Westinghouse, Service Engineering Department at (773) 483-7575